



METER RELATED ACCESSORY PARTS

**DESIGNED TO FIT STOCK METER!
MULTI-FUNCTIONAL INDICATOR NEWLY RELEASED!**

**COUPLER-ON!
HARNESS MODIFICATION
NOT REQUIRED!!**



**DISPLAY HAS EXCELLENT VISIBILITY
WITHOUT INTERFERING WITH RIDING!**

NEW LINE UP!!

MONKEY 125 (JB03/JB05)

**CT125 · HUNTER CUB
(FNo.JA65-1000001~1099999)**

DAX 125 (JB04)

**CT125 · HUNTER CUB
(FNo.JA65-1100001~)**

DAX 125 (JB06)

○ GEAR POSITION INDICATOR DISPLAY FUNCTION

Contact-type gear position sensor can display instantly which gear the rider is in just after gear changing.



Display depends on models.

○ SHIFT UP INDICATOR FUNCTION

Once set rpm for each gear, 7-segment-display flash at rpm for shift up and allows shift change.



Flash RPM setting for each gear possible.

○ VOLTAGE DISPLAY FUNCTION

When turning on the power, the opening demo screen will be displayed.
EX : 12.5V



※Display or non-display selectable.

SETTING BUTTON

Press and hold the setting button on the back of the unit for parameter.



MAIN UNIT
(gear position indicator)



“KITACO”
is laser marked.

○ BAR GRAPH TACHOMETER DISPLAY FUNCTION

The engine RPM is displayed in a flowing bar graph format.

8 high-brightness leds adopted,
invisibility improves day or night.



A, START 1,000rpm STEP
B, START 3,000rpm/
1,000rpm STEP
C, START 2,500rpm/
500rpm STEP

○ OVER REV DISPLAY FUNCTION

If the displayed RPM is exceeded, the bar graph will flash.
Indicates engine being in over rev.



3 flash setting patterns
available : No flash,
Only red bar graph flash,
All the bar graph flash.

○ TIMER DISPLAY FUNCTION

The elapsed time since power was turned on can be displayed on a bar graph up to a maximum of 3 hours and 50 minutes.

RED LED LIGHTING
1 LED...1 H
LOWER SIDE ...1 H
UPPER SIDE ...2 H
BOTH SIDES ...3 H

GREEN LED LIGHTING
1 LED...10 MIN
3 LED...30 MIN



※The bar graph tachometer will not function when the timer display function is in use.

※The LED brightness can be adjusted in 5 levels.

